3 IN 1 AUTO-DETECTOR

- O Power LED (It lights when power is on)
- LowBat LED (It lights when the capacity of the battery is low)
- Voltage LED (It lights when the Detector detects the wire)
- Metal LED (It lights when the Detector detects metal)
- G Stud LED (It lights when the Detector detects wood)
- Mode switch
- Power button (Power can be turned on when the button is pressed)
- Battery cover
- Sensor

Preparing the detector for use

- Slide off the battery cover on the back of the unit and connect a fresh 12V battery (not supplied). Ensure battery is fitted in the correct manner. Note Positive (+) and negative (-) connections.
- Restore the cover and securely snap in place, now the detector is ready for use.
- Keep your free hand at least 6 inches away from the unit or scanning surface while testing.

